## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47251	Main Street: CRANBERRY_WOODS_CT				Cross Street: RASPBERRY_KNOLL_DR				Location:	S
ADA ID: A2F6EC7C25	C7C25D0 Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description			Data Compliance Description		
	Paul Incor	Remove & Re	Replace Entire Ramp	n.	N/A	Ramp Length (in)	46.0	No	Ramp Slope (%)	9.6
Contract.				P.	No	Ramp Width (in)	45.0	No	Ramp XSlope (%)	4.2
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	- Ent				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
CHA MA	A. MONT				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
RASPEEDEN					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Nou	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A DA ALAN	6	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	6. m	177			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Sand a state	-			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and the second second	1. Marine Fr				N/A	Shared Landing?	N/A			
A State of the second		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A REAL AND CAL		F	304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
1.1.7 7 T. MA	in the first	R304.5.3		,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
end , essent	Litter Aller					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
	The second second				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	RASPBERRY KNOLL DR					X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A		Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00	1975	Obstruction Type	174		Storm Grate/Utility Type	10/5
		10121 0001.	Ψ				N/A			N/A
							IN/A	1		11/1

Yes Surface Condition? (G/P)

Good

