## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3841	Main Sti	reat: CHIMNEY SPRIN		Cross Stree		GROVE DR		Location:	NW
	Main Street: CHIMNEY_SPRINGS_PL			Cross Street: POPLAR_GROVE_DR					
ADA ID: A2FE2A81C515 Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data			Comp	Compliance Description Dat	
A HANK AND	R	Remove & Replace	Entire Ramp.	N/A	Ramp Lengt	h (in) 50.0	Yes	Ramp Slope (%)	5.8
			•	No	Ramp Width	(in) <b>47.0</b>	No	Ramp XSlope (%)	6.8
A DE TO	SA LIN			N/A	Flare Type L	T N/A	N/A	Flare Type RT	N/A
A CONTRACTOR OF				N/A	Flare Slope	LT (%) N/A	N/A	Flare Slope RT (%)	N/A
the Maria F				N/A	Flare Traver	sable LT? N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Len	igth (in) N/A	N/A	DWS Provided?	N/A
E CAR	We we t	Surveyor Notes:		N/A	Landing Wid	lth (in) N/A	N/A	DWS Contrast?	N/A
Rob		N/A		N/A	Landing Slo	pe (%) N/A	N/A	DWS Length (in)	N/A
COL	RGROVEDR			N/A	Landing X S	lope (%) N/A	N/A	DWS Full Width?	N/A
in the k	0-00-0			N/A	Landing Cur	b? (Y/N) N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Land	ding? N/A			
	NO. THE NO.	PROW/ADA:		N/A	Gutter Pond	ling? N/A	N/A	Gutter Slope (%)	N/A
	T PI	Not Found, R304.5.	1, R304.5.3	N/A	Gutter Lip H	t (in) N/A	N/A	Gutter X Slope (%)	N/A
	A AND AND	,	,	N/A	Painted X W	/alk1? No	N/A	Painted X Walk2?	N/A
A CONTRACTOR	Y' CHI LA	9			X Walk 1 Dir	rection To E		X Walk 2 Direction	N/A
A STATION AND	A PARA			N/A	X Walk 1 Wi	dth (in) N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name C	HIMNEY SPRINGS PL				X Walk 1 Slo	ope (%) 6.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X S	Slope (%) 0.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside	XWalk1? N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope	(%) N/A	N/A	Clear Space?	N/A
					Road X Slop	oe (%) N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstruc	tions? N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 18	350.00	Obstruction	Туре		Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

