## cole

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



9.0

No

Curb Slope (%)

Intersection ID: N/A Main Street: MARTIN_LUTHER_KING_JR_BCross Street: N/A									Location:	w
ADA ID: A33FD219872E	Ramp Type: BlendTrans1				Pass/Fa	ail: Pass Overall	Severity Score:	0		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Comp	Compliance Description		Comp	liance Description	Data
		Remove & Replace Curt			N/A	Ramp Length (in)	60.0	Yes	BlendTrans Slope (%)	0.7
		Two New Directional Ramps o Equivalent. Remove & Replac Gutter.			Yes	Ramp Width (in)	96.0	Yes	BlendTrans XSlope (%)	2.0
			Replace	e	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
					N/A	Flare Slope LT (%)	8.6	N/A	Flare Slope RT (%)	3.7
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
					Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes
		Surveyor Notes:			Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
	1 Carlor	N/A			No	Landing Slope (%)	2.7	Yes	DWS Length (in)	24.0
	C 187 1				Yes	Landing X Slope (%)	0.9	Yes	DWS Full Width?	Yes
E V				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	6.0	
				N/A	Shared Landing?	No				
A A A A A A A A A A A A A A A A A A A	1	PROW/ADA: Not Found, R304.2.2-Perp, R304.3.2- Para, R305.2, R304.5.3			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.7
The second and the	1 3				Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.2
	and the second second				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To N	
					X Walk 1 Width (in)	93.5		X Walk 2 Width (in)	N/A	
Street 1 Name ENT	RANCE	-				X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	4.8
Stop Condition-Street 1 S	topSign					X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	0.9
Street 2 Name MARTIN LUTHER KING JR BLVD					Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None					Road Slope (%)	1.8		Clear Space?	Yes
						Road X Slope (%)	4.2	N/A	Clear Space to XWalk (in)	N/A
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost:	\$	3950.00		Obstruction Type			Storm Grate/Utility Type	
						• •	N/A			N/A
								Yes	Surface Condition? (G/P)	Good





