

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

0.0

0.0

N/A

0.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

1.1

0.3

N/A

N/A

N/A

N/A

1.1

Good

Intersection ID: 12473 Main Street: S_CLARKSON_ST Cross Street: W_PALMER_ST Location: E

ADA ID: A34811F0FD2A Ramp Type: Directional2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

N/A N/A

Compliance Description

Grade Break?

Flare Type RT

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset LT (in)

DWS Offset RT (in)

Gutter Slope (%)

Road Slope (%)

Clear Space?

Road X Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

Storm Grate/Utility Hazard?

Gutter X Slope (%)

Flare Traversable RT?

Grade Break Slope (%)

Grade Break XSlope (%)

Data

39.0

40.0

5.1

2.7

N/A

N/A

N/A

0.0

0.0

0.0

0.0

N/A

N/A

0.0

0.0

No

N/A

1.1

0.3

N/A

N/A

To SW



Street 1 Name

Stop Condition-Street 1

Stop Condition-Street 1

None

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Possible Solutions: Compliance Description N/A Ramp Length (in) Remove & Replace Entire Ramp. No Ramp Width (in) Yes Ramp Slope (%) No Ramp XSlope (%) N/A Flare Type LT N/A Flare Slope LT (%) Surveyor Notes: N/A Flare Traversable LT? N/A N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) PROW/ADA: N/A Landing Curb? (Y/N) R304.5.1, R304.5.3 N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%)





Total Cost:



N/A

N/A

1800.00

Ramp inside XWalk1?

Any Obstructions?

Obstruction Type