## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21221	Main Street: SHARON_RD			reet:	SULKIRK_RD	Location:	NW			
ADA ID: A3630C64B065	Ramp Type: PerpDiag				I Compliance: No		o Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Comp	liance Description	Data Compliance Description			Data	
		Remove & Replace Curb Ramp W	-	N/A	Ramp Length (in)	54.0	No	Ramp Slope (%)	9.8	
		Two New Directional Ramps or		/es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.2	
		Equivalent.	N	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
P P			1	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			1	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:	1	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A	1	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
SULKIRK RD			1	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
The sect of the sector			1	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	SIC AS			N/A	Shared Landing?	N/A		ζ,		
	and the second	PROW/ADA:	1	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	No Into	R304.2.2, R304.5.3		I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			1	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	1/21				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
Sendary 1 - 125	40,		1	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	SULKIRK RD	-			X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	4.5	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.5		X Walk 2 X Slope (%)	0.2	
Street 2 Name	SHARON RD		1	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	2.5	N/A	Clear Space?	N/A	
					Road X Slope (%)	5.2	N/A	Clear Space to XWalk (in)	N/A	
			1	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	

