

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52610Main Street: LEGRANGER_RDCross Street: HERITAGE_POND_DRLocation:NWADA ID: A37DFCA0BE6DRamp Type: Directional1Initial Pass/Fail: FailOverall Compliance: NoSeverity Score: 13.75

ADA ID: A37DFCA0BE6D Ramp Type: Directional1			Initial	Pass/F	ail: Fail Overall (Complian	ce: N	o Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data		
	1	Remove & Replace Entire Ram	p.	N/A	Ramp Length (in)	110.0	N/A	Grade Break?	N/A		
	ĺ	·	-	Yes	Ramp Width (in)	71.0	N/A	Grade Break Slope (%)	0.0		
				No	Ramp Slope (%)	8.7	N/A	Grade Break XSlope (%)	0.0		
1				Yes	Ramp XSlope (%)	3.4					
-				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
8				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
•		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
E. E.		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A		
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A		
		R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A		
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
				N/A	Painted X Walk1?	No		Road Slope (%)	2.6		
Street 1 Name	LEGRANGER RD				X Walk 1 Direction	To E		Road X Slope (%)	6.4		
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A		
Street 2 Name	N/A				X Walk 1 Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A		
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	6.4	N/A	Storm Grate/Utility Hazard?	N/A		
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type			
				N/A	Any Obstructions?	N/A			N/A		
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good		
						N/A	N/A	Curb Slope (%)	N/A		





