## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: PINEVILLE-MATTHEWS RD Cross Street: N/A Location: SE									
Intersection ID: N/A Main Street: PINEVILLE-MATTHEWS_RD								Location:	SE
ADA ID: A38CD855EF0B Ramp Type: PerpDiag			Initial I	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	E. P. CHARLES ESDER	Possible Solutions:		Compliance Description Da		Data	a Compliance Description		Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	63.0	No	Ramp Slope (%)	9.0
March Real		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.0
		È Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
1 Leans				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	EMAITCHENS RD			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
DINEVILLE	MATOME			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
- in the second second	Martin Martine	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	E. States	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
PROW/ADA: Not Found, R304.2.2, R304.5.3				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To N		X Walk 2 Direction	To W
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PINEVILLE-MATTHEWS RD	_			X Walk 1 Slope (%)	7.7		X Walk 2 Slope (%)	3.7
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	5.7		X Walk 2 X Slope (%)	10.3
Street 2 Name	ENTRANCE			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	6.8	N/A	Clear Space?	N/A
					Road X Slope (%)	9.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					<i>.</i>	N/A		5 51	N/A

es Surface Condition? (G/P)

Good

