

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•		- /					
Intersection ID: 25477 Main Street: FIVE_KNOLLS_DR			C	Cross Street: REA_RD				Location:	NE
ADA ID: A3A56603FFD2 Ramp Type: Perp			I	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
	HAR STOR	Remove & Replace Entire R	amp.	N/A	Ramp Length (in)	71.0	No	Ramp Slope (%)	9.7
	All and a		p-	Yes	Ramp Width (in)	69.0	Yes	Ramp XSlope (%)	1.3
	CALL-			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	111			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	the			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1. No. 1	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	The second	N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
FIXE_KNOLLS_DR	Carlo Barrella			N/A	Shared Landing?	N/A			10/4
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Contraction of Contraction	S. Descret			N/A	8	N/A			N/A
		Not Found, R304.2.2		N/A N/A	Gutter Lip Ht (in) Painted X Walk1?	N/A No	N/A	Gutter X Slope (%) Painted X Walk2?	N/A N/A
	the base where the			N/A			N/A		
a solution and the solution of					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
		1		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	REA RD				X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A		Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	5 1850	0.00	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

