cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

9.1

| Intersection ID: 10032880 | : 10032880 Main Street: NATIONS_FORD_RD | | | s Street: | N/A | Location: | SW | | |
|---|---|---------------------------|---------|---|----------------------|-----------|--------------------|-----------------------------|-------|
| ADA ID: A3BB8482DED9 | DA ID: A3BB8482DED9 Ramp Type: ParaDiag | | | nitial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 26.25 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | Compliance Description Data Complia | | | liance Description | Data | |
| | | Remove & Replace Curb Ra | mp With | N/A | Ramp Length LT (in) | 72.0 | N/A | Ramp Length RT (in) | 55.0 |
| | 11000 | Two New Directional Ramps | • | Yes | Ramp Width LT (in) | 108.0 | Yes | Ramp Width RT (in) | 108.0 |
| | 11100 | Equivalent. | | No | Ramp Slope LT (%) | 14.9 | Yes | Ramp Slope RT (%) | 5.0 |
| | 11/2 1 | | | No | Ramp XSlope LT (%) | 4.9 | No | Ramp XSlope RT (%) | 3.0 |
| | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | 6. | Surveyor Notes: | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| <u>ь</u> | | N/A | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | 4 | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | N/A | Shared Landing? | N/A | | | |
| | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| | 1 AT | PROW/ADA: | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | | R304.3.2, R304.5.3 | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| the second have | | | | X Walk 1 Direction | To SE | | X Walk 2 Direction | To NE | |
| | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | | | | | X Walk 1 Slope (%) | 1.4 | | X Walk 2 Slope (%) | 5.4 |
| Street 1 Name NAT | TIONS FORD RD | | | | X Walk 1 X Slope (%) | 3.7 | | X Walk 2 X Slope (%) | 1.7 |
| Stop Condition-Street 1 | None | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Street 2 Name | ENTRANCE | | | | Road Slope (%) | 6.3 | N/A | Clear Space? | N/A |
| Stop Condition-Street 2 | Signal | | | | Road X Slope (%) | 3.1 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | Total Cost: \$ | 3200.00 | | | N/A | | | N/A |
| | | | | | | | Yes | Surface Condition? (G/P) | Good |

