## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44221	ntersection ID: 44221 Main Street: ATHERTON_MILL_RD			Cross Street: RICHARD_ROZZELLE_DR				Location:	NE
ADA ID: A3FE6BBB97	88 Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: N				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	-	Possible Solutions:		Compliance Description		Data	Data Compliance Description		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	73.0	Yes	Ramp Slope (%)	5.3
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	40.5	No	Ramp XSlope (%)	2.4
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	- I I I			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
E				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	THELE DR 6	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		174		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
RIGHTER				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A	1		
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Sampellin 200				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		R304.5.1, R304.5.3		N/A	Painted X Walk1?	N/A No	N/A	Painted X Walk2?	N/A No
PROW/ADA: R304.5.1, R304.5.3				N/A	X Walk 1 Direction	To W	N/A	X Walk 2 Direction	To S
				N/A		-	<b>N</b> 1/A		
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ATHERTON MILL RD				X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	12.1
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	2.9
Street 2 Name	RICHARD ROZZELLE DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	0.3	N/A	Clear Space?	N/A
					Road X Slope (%)	9.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

es Surface Condition? (G/P)

Good

