

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 18180	Main Street: FAIRBLUFF_PL	Cross Street: ZEPHYR_LN	Location:	E
ADA ID: A44F9F9F8F64	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 37.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	6.4
	Remove & Replace Gutter.		Yes	Ramp Width (in)	63.0	Yes	Ramp XSlope (%)	0.9
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	13.0	No	Flare Slope RT (%)	12.3
			N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
			No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
			No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
			No	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0
			No	Landing X Slope (%)	N/A	No	DWS Full Width?	No
Surveyor Notes:		No	Landing Curb? (Y/N)	No	No	DWS Offset (in)	7.0	
N/A		N/A	Shared Landing?	No				
PROW/ADA:		Yes	Gutter Ponding?	No	No	Gutter Slope (%)	6.5	
R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R304.2.3, R305.1.4, R305.2, R302.7.2, R304.5.4		No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	0.9	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
			X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	N/A	
			X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A	
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	N/A	N/A	Clear Space?	Yes	
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
			Obstruction Type			Storm Grate/Utility Type		
					N/A		N/A	
					Yes	Surface Condition? (G/P)	Good	
Total Cost:		\$	2600.00					
Street 1 Name		ZEPHYR LN						
Stop Condition-Street 2		StopSign						
Street 2 Name		N/A						
Stop Condition-Street 1		N/A						

