

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

6.0

2.3

N/A

N/A

N/A

Main Street: BALLANTYNE COMMONS PY Cross Street: BALLANTYNE FOREST DR Intersection ID: 27530 Location: NW **Severity Score:** 10 ADA ID: A484DFCDB6E4 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** 

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

Yes

No

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

Flare Traversable RT?

Data

127.0


47.0

N/A

N/A

N/A

Flare Traversable LT?



**BALLANTYNE COMMONS PY** Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:	Compli	ance	Descri	iption
Remove & Replace Entire Ramp.	N/A	Ramp Lengt		າ (in)
·	No	Ramp	Width	(in)
	N/A	Flare	Type L	Т
	N/A	Flare	Slope L	_T (%)
	N/A	Flare	Travers	sable L1
	N/A	Landi	ing Leng	gth (in)
Surveyor Notes:	N/A	Landi	ing Widt	:h (in)
N/A	N/A	Landi	ing Slop	e (%)
	N/A	Landi	ing X Sl	ope (%
	N/A	Landi	ing Curb	? (Y/N
	N/A	Share	ed Land	ing?
PROW/ADA:	N/A	Gutte	er Pondi	ng?
Not Found, R304.5.1, R304.5.3	N/A	Gutte	r Lip Ht	(in)
	N/A	Paint	ed X Wa	alk1?
		X Wa	lk 1 Dire	ection
	N/A	X Wa	lk 1 Wid	łth (in)
		X Wa	lk 1 Slo	pe (%)
		X Wa	lk 1 X S	lope (%
	N/A	Ramp	inside	XWalk <sup>2</sup>
		Road	Slope (	(%)





