cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47384	ection ID: 47384 Main Street: BRIDGEWALK_DR			Cross	Street:	ARDREY_KELL_RD	Location:	NW		
ADA ID: A4BBD44F29CE	044F29CE Ramp Type: PerpDiag			Initial	Pass/Fa	ail: Fail Overall	o Severity Score:	10		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description		Data	Comp	liance Description	Data
		Remove & Replace Curb F	Ramr	With	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	7.8
		Two New Directional Ram	-		No	Ramp Width (in)	45.0		Ramp XSlope (%)	3.0
		Equivalent.	P • • •		N/A	Flare Type LT	N/A		Flare Type RT	N/A
		3			N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
Jam Re					N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
3 and - Same				N/A	Landing Length (in)		N/A	DWS Provided?	N/A	
	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
R. A.	N/A			N/A	Landing Slope (%)		N/A	DWS Length (in)	N/A	
All all and the second	0/8			N/A	Landing X Slope (%)	N/A		DWS Full Width?	N/A	
PROW/ADA:				N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A		2		
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A	
Not Found, R304.5.1, R304.5.3					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					N/A	X Walk 1 Direction	To S		X Walk 2 Direction	To E
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	ARDREY KELL RD	-			N/A	X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	5.3
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	0.3
Street 2 Name	BRIDGEWALK DR				N/A	Ramp inside XWalk1?		N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				N/A	Road Slope (%)	3.2		Clear Space?	N/A
	otopolyn					Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00	11/5	Obstruction Type	N/A		Storm Grate/Utility Type	11/2
			Ψ	5200.00			N/A		Storm Oraco/Ounty Type	N/A
							IN/A			11/1

Yes Surface Condition? (G/P)

Good

