

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10026073Main Street: ENDERLY\_RDCross Street: N/ALocation:EADA ID: A4E7BB48A65FRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 12.5

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



A STATE OF THE REAL PROPERTY O	
Street 1 Name	ENDERLY RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:						
Remove & Replace Entire Ramp.						
Surveyor Notes:						
N/A						
PROW/ADA:						
R304.2.2						
R304.2.2						

Total Cost:	\$ 1850.00

Comp	iance Description	Data	Comp	liance Description	n Data
N/A	Ramp Length (in)	56.0	No	Ramp Slope (%)	9.1
Yes	Ramp Width (in)	49.0	Yes	es Ramp XSlope (%)	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%	) N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable	RT? N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%	) <b>N/A</b>
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in	) <b>N/A</b>
	X Walk 1 Slope (%)	7.0		X Walk 2 Slope (%	) N/A
	X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWa	lk2? <b>N/A</b>
	Road Slope (%)	N/A	N/A	N/A Clear Space?	
	Road X Slope (%)	N/A	N/A	Clear Space to XV	Valk (in) N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility	Hazard? N/A
	Obstruction Type		Storm Grate/Utility Type		<sup>,</sup> Туре
		N/A			N/A
			Yes	Surface Condition	? (G/P) <b>Good</b>





