

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

59.0

59.0

7.5

2.0

9.0

7.6

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

23.3

Intersection ID: 9068 Main Street: W_TRADE_ST Cross Street: ROZZELLES_FERRY_RD Location: NW

ADA ID: A4EC2F9AB085 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 46.25

Compliance Description

N/A

Yes

Yes

Yes

N/A

No

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Nο

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Curb Slope (%)

Flare Traversable RT?

Data

59.5

59.0

8.2

0.4

73.0

46.5

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A



Street 1 Name
YieldSign
Stop Condition-Street 1
IDAHO DR
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3



Total Cost:



1800.00

Shared Landing? N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? Yes Painted X Walk2? N/A To SE X Walk 1 Direction X Walk 2 Direction N/A X Walk 1 Width (in) 111.0 X Walk 2 Width (in) N/A X Walk 2 Slope (%) 6.3 N/A X Walk 1 Slope (%) X Walk 1 X Slope (%) 7.7 X Walk 2 X Slope (%) N/A Ramp inside XWalk1? Yes N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good