

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 22882Main Street: SARDIS_POINTE_RDCross Street: SARDIS_RDLocation: NWADA ID: A5D523FA4410Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
None
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:	Co
Remove & Replace Entire Ramp.	N/A
•	Yes
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
R304.2.2, R304.5.3	N/A
,	N/A
	N/A
	N/A

Total Cost: \$ 1850.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	oliance Description	Data	
N/A	A Ramp Length (in)	47.0	No	Ramp Slope (%)	9.2	
Ye	s Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.2	
N/A	A Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	A Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	A Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	A Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	A Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	A Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	A Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	A Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	A Shared Landing?	N/A				
N/A	A Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	A Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A	
N/A	A Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	





