cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

7.8

Intersection ID: 21272	Main Str		C ===	a Stract				Location:	N
Intersection ID: 31372		Main Street: GREENWAY_VISTA_LN		Cross Street: MCINTYRE_RIDGE_DR					
ADA ID: A614DCC80FC0	Ramp Ty	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	33.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Comp	Compliance Description		Data Compliance Description		Data
		Remove & Replace Curb Ra	amp With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	2.3
		Two New Directional Ramp	Ramps or	No	Ramp Width (in)	36.0	No	BlendTrans XSlope (%)	9.0
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	3			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A A A A A A A A A A A A A A A A A A A	18 A			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
a transfer of the	ST B SON			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Steen St		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
BALL OF BALL	have be	GTR GAP 1.0, CURB GAP/	.IP 1.0	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	AN CO	,		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E To A				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	ALL NO SM			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
	A CAN				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name MC	INTYRE RIDGE DR				X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	2.4
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	4.1
Street 2 Name GR	EENWAY VISTA LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	5.0		Clear Space?	N/A
					Road X Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P) No Curb Slope (%)





