

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 13725 Main Str         | Cross Street: N_SHARON_AMITY_RD |  |                       |      | Location:                   | NW                          |      |
|---|---------------------------------|--|-----------------------|------|-----------------------------|-----------------------------|------|
|   | Main Street: AUBURNDALE_RD      |  |                       |      |                             |                             |      |
| ADA ID: A62D390372D5 Ramp Type: Perp    |                                 | Initial Pass/Fail: Fail Overall Compliance: No |                       |      | o Severity Score:           | 22.5                        |      |
| Codes/Mitigation Info/Possible Solution |                                 | Field Measurements/Component Compliance        |                       |      |                             |                             |      |
|   | Possible Solutions:             | Compliance Description Data                    |                       |      | Compliance Description Data |                             |      |
|   | Remove & Replace Entire Ramp.   | N/A  | Ramp Length (in)      | 59.0 | No                          | Ramp Slope (%)              | 11.2 |
|   |                                 | No   | Ramp Width (in)       | 44.0 | No                          | Ramp XSlope (%)             | 4.4  |
|   |                                 | N/A  | Flare Type LT         | N/A  | N/A                         | Flare Type RT               | N/A  |
| AUBURNDALE ROSE E                       |                                 | N/A  | Flare Slope LT (%)    | N/A  | N/A                         | Flare Slope RT (%)          | N/A  |
|   |                                 | N/A  | Flare Traversable LT? | N/A  | N/A                         | Flare Traversable RT?       | N/A  |
|   |                                 | N/A  | Landing Length (in)   | N/A  | N/A                         | DWS Provided?               | N/A  |
|   | Surveyor Notes:                 | N/A  | Landing Width (in)    | N/A  | N/A                         | DWS Contrast?               | N/A  |
|   | N/A                             | N/A  | Landing Slope (%)     | N/A  | N/A                         | DWS Length (in)             | N/A  |
|   |                                 | N/A  | Landing X Slope (%)   | N/A  | N/A                         | DWS Full Width?             | N/A  |
|   |                                 | N/A  | Landing Curb? (Y/N)   | N/A  | N/A                         | DWS Offset (in)             | N/A  |
|   |                                 | N/A  | Shared Landing?       | N/A  |                             |                             |      |
|   | PROW/ADA:                       | N/A  | Gutter Ponding?       | N/A  | N/A                         | Gutter Slope (%)            | N/A  |
|   | Not Found, R304.5.1, R304.2.2,  | N/A  | Gutter Lip Ht (in)    | 0.5  | N/A                         | Gutter X Slope (%)          | N/A  |
|   | R304.5.3                        | N/A  | Painted X Walk1?      | No   | N/A                         | Painted X Walk2?            | N/A  |
|   |                                 |  | X Walk 1 Direction    | To S |                             | X Walk 2 Direction          | N/A  |
|   |                                 | N/A  | X Walk 1 Width (in)   | N/A  | N/A                         | X Walk 2 Width (in)         | N/A  |
| Street 1 Name AUBURNDALE RD             | -                               |  | X Walk 1 Slope (%)    | 2.0  |                             | X Walk 2 Slope (%)          | N/A  |
| Stop Condition-Street 2 StopSign        |                                 |  | X Walk 1 X Slope (%)  | 2.1  |                             | X Walk 2 X Slope (%)        | N/A  |
| Street 2 Name N/A                       |                                 | N/A  | Ramp inside XWalk1?   | N/A  | N/A                         | Ramp inside XWalk2?         | N/A  |
| Stop Condition-Street 1 N/A             |                                 |  | Road Slope (%)        | N/A  | N/A                         | Clear Space?                | N/A  |
|   |                                 |  | Road X Slope (%)      | N/A  | N/A                         | Clear Space to XWalk (in)   | N/A  |
|   |                                 | N/A  | Any Obstructions?     | N/A  | N/A                         | Storm Grate/Utility Hazard? | N/A  |
|   | Total Cost: \$ 1                | 850.00   | Obstruction Type      |      |                             | Storm Grate/Utility Type    |      |
|   |                                 |  |                       | N/A  |                             |                             | N/A  |

s Surface Condition? (G/P)

Good

