cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46818	Main Str	Main Street: HOLM_OAK_PL			AZALEA_HILLS_DR	Location:	NE		
ADA ID: A6569660C384	Ramp Ty	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	31	Possible Solutions:		Compliance Description D			ata Compliance Description		Data
		Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent.	With	N/A	Ramp Length (in)	46.0	No	Ramp Slope (%)	11.2
ACTI				Yes	Ramp Width (in)	48.5	No	Ramp XSlope (%)	6.8
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	VALEA HILLS DR	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E Contraction of the contraction		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A B				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E PA			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
the second second			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
The second	·····, ·····		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To W		X Walk 2 Direction	To S
100			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	HOLM OAK PL				X Walk 1 Slope (%)	5.5		X Walk 2 Slope (%)	2.9
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	4.0
Street 2 Name	AZALEA HILLS DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	5.6	N/A	Clear Space?	N/A
					Road X Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

