


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 15889	Main Street: HERTFORD_RD	Cross Street: PEMBROKE_AV	Location: SE
ADA ID: A66DE2533142	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 37.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
 <p>Street 1 Name PEMBROKE AV</p> <p>Stop Condition-Street 1 StopSign</p> <p>Street 2 Name N/A</p> <p>Stop Condition-Street 2 N/A</p>	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	51.0	
			Yes	Ramp Width (in)	48.0	
			No	Ramp Slope (%)	12.5	
			No	Ramp XSlope (%)	6.1	
			N/A	Flare Type LT	N/A	
			N/A	Flare Slope LT (%)	N/A	
			N/A	Flare Traversable LT?	N/A	
			N/A	Landing Length (in)	0.0	
			N/A	Landing Width (in)	0.0	
			N/A	Landing Slope (%)	0.0	
			N/A	Landing X Slope (%)	0.0	
			N/A	Landing Curb? (Y/N)	N/A	
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	0.0	
			N/A	Gutter Lip Ht (in)	0.0	
			N/A	Painted X Walk1?	No	
				X Walk 1 Direction	To N	
				X Walk 1 Width (in)	N/A	
				X Walk 1 Slope (%)	8.1	
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.2.2, R304.5.3</p>						
				X Walk 1 X Slope (%)	2.2	
			N/A	Ramp inside XWalk1?	N/A	
			N/A	Any Obstructions?	N/A	
Total Cost:		\$ 1600.00		Obstruction Type		
					Yes	Surface Condition? (G/P)
					N/A	Curb Slope (%)
						Good
						10.0

