

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



								L C	
Intersection ID: 9343	Main Street: CAMPUS_ST			Cross Street: SANDERS_AV				Location:	E
ADA ID: A68DEF523E52 Ramp Type: Directional1		Initi	Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	a The	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Entire Ra	amp.	N/A	Ramp Length (in)	47.0	N/A	Grade Break?	N/A
		-	-	Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
				Yes	Ramp Slope (%)	7.6	N/A	Grade Break XSlope (%)	0.0
	-			No	Ramp XSlope (%)	5.1			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	「「金田」の			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
El El Com	- 0 1	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	the second	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
SANDERS A	V C			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	T Kenne			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	· COLUMN			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	8.1
Street 1 Name	CAMPUS ST				X Walk 1 Direction	To W		Road X Slope (%)	6.7
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	8.1	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	6.7	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	8.0

