


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9653	Main Street: EDISON_ST	Cross Street: WOODWARD_AV	Location: NW
ADA ID: A6C27B94D970	Ramp Type: ParaDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length LT (in)	25.5
			Yes	Ramp Width LT (in)	75.5
			Yes	Ramp Slope LT (%)	1.1
			No	Ramp XSlope LT (%)	2.7
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
<p>Surveyor Notes:</p> <p>LT RP < 5%; CURB GAP 1.0</p> <p>PROW/ADA:</p> <p>R304.5.3, R304.3.2</p>			N/A	Ramp Length RT (in)	45.0
			Yes	Ramp Width RT (in)	60.0
			No	Ramp Slope RT (%)	11.7
			Yes	Ramp XSlope RT (%)	1.9
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Slope (%)	N/A
<p>Street 1 Name</p> <p>WOODWARD AV</p> <p>Stop Condition-Street 1</p> <p>None</p> <p>Street 2 Name</p> <p>EDISON ST</p> <p>Stop Condition-Street 2</p> <p>StopSign</p>			N/A	Gutter X Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To S
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	2.8
				X Walk 1 X Slope (%)	4.7
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	4.7
				Road X Slope (%)	2.7
<p>Total Cost:</p> <p>\$ 3200.00</p>			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
			N/A	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	12.9

