


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10032958		Main Street: NEW RENAISSANCE_WY	Cross Street: N/A	Location:	SW
ADA ID: A6F7B3A04F78		Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 1.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	52.0
			Yes	Ramp Width (in)	72.0
			Yes	Ramp Slope (%)	1.9
			No	Ramp XSlope (%)	3.6
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	0.0
			N/A	Landing Width (in)	0.0
Surveyor Notes:		Compliance	Description	Data	
N/A		N/A	Flare Slope RT (%)	N/A	0.0
		N/A	Flare Traversable RT?	N/A	N/A
		N/A	DWS Provided?	N/A	N/A
		N/A	DWS Contrast?	N/A	N/A
		N/A	DWS Length (in)	N/A	N/A
		N/A	DWS Full Width?	N/A	N/A
		N/A	DWS Offset LT (in)	N/A	N/A
		N/A	DWS Offset RT (in)	N/A	N/A
		N/A	Gutter Slope (%)	N/A	N/A
		N/A	Gutter X Slope (%)	N/A	N/A
		N/A	Road Slope (%)	2.6	
		N/A	Road X Slope (%)	2.4	
		N/A	Clear Space?	N/A	
		N/A	Clear Space to XWalk (in)	N/A	
		N/A	Storm Grate/Utility Hazard?	N/A	
		N/A	Storm Grate/Utility Type		
		N/A	Surface Condition? (G/P)	Good	
		N/A	Curb Slope (%)	5.4	
PROW/ADA:					
R304.5.3					
Total Cost:		\$	1600.00		
Street 1 Name	ENTRANCE				
Stop Condition-Street 1	StopSign				
Street 2 Name	N/A				
Stop Condition-Street 2	N/A				

