

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21144Main Street:COLONY\_ACRES\_DRCross Street:HILARY\_CRLocation:NWADA ID: A707B9E5717BRamp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:12.5

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

COLONY ACRES DR StopSign NATIONS FORD RD None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.2.2

Total Cost: \$ 3200.00

Field Measurements/Component Compliance						
Compliance Description			Data	Com	oliance Description	Data
N	I/A	Ramp Length (in)	43.0	No	Ramp Slope (%)	10.2
Υ	'es	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.6
N	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N	I/A	Shared Landing?	N/A			
N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To SE		X Walk 2 Direction	To E
N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	6.5
		X Walk 1 X Slope (%)	6.6		X Walk 2 X Slope (%)	0.5
N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	2.1	N/A	Clear Space?	N/A
		Road X Slope (%)	7.4	N/A	Clear Space to XWalk (in)	N/A
N	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good
0.12						





