


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 11543	Main Street: GRACE_ST	Cross Street: LOLA_AV	Location: NW
ADA ID: A786BA32431A	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 42.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance										
<div></div> <div>Street 1 NameGRACE ST</div> <div>Stop Condition-Street 2None</div> <div>Street 2 NameLOLA AV</div> <div>Stop Condition-Street 1StopSign</div>			Possible Solutions:			Compliance			Description			Data	
			Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.			N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	6.5		
						No	Ramp Width (in)	34.0	No	Ramp XSlope (%)	11.2		
						N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
						N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
						N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
						N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
						N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
						N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
						N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
Surveyor Notes:  N/A			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A					
			N/A	Shared Landing?	N/A								
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A					
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A					
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No					
				X Walk 1 Direction	To S		X Walk 2 Direction	To E					
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A					
				X Walk 1 Slope (%)	7.6		X Walk 2 Slope (%)	1.2					
				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	8.0					
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A					
PROW/ADA:  R304.5.1, R304.5.3				Road Slope (%)	7.0	N/A	Clear Space?	N/A					
				Road X Slope (%)	6.8	N/A	Clear Space to XWalk (in)	N/A					
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A					
				Obstruction Type			Storm Grate/Utility Type						
					N/A			N/A					
						Yes	Surface Condition? (G/P)	Good					

