

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

15.0

0.5

N/A

N/A

N/A

Intersection ID: 3653 Main Street: TAVERNAY PY Cross Street: TREYMORE LN Location: SE **Overall Compliance: No Severity Score:** 25 **ADA ID: A78CFB3C2326** Ramp Type: Perp Initial Pass/Fail: Fail

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Flare Traversable LT?

Flare Type LT

N/A

Yes

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

Flare Traversable RT?

Data

26.5

48.0

N/A

N/A

N/A



Street 1 Name Stop Condition-Street 2 Street 2 Name

Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: R304.2.2



