

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

8.6

1.7

N/A

Good

Main Street: FLAT CREEK DR Intersection ID: 28142 **Cross Street: LONGMONT DR** Location: NW **Overall Compliance: No** ADA ID: A79F08477316 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 12.5

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

58.0

48.5

N/A

No

To SE

N/A

4.1

1.4

N/A

N/A

N/A

N/A

N/A

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

**Obstruction Type** 

Flare Traversable LT?



**FLAT CREEK DR** Street 1 Name Stop Condition-Street 2 None N/A N/A

rossible solution		i ieiu ivie
Possible Solutions:	Comp	liance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
·	Yes	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%
	N/A	Landing Curb? (Y/N
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
Not Found, R304.2.2	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%
	N/A	Ramp inside XWalk
		Road Slope (%)

do.
and the same of th

Total Cost:



N/A

1850.00

