cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			-		-					
Intersection ID: 50584	Main Str	Main Street: GREAT_LAUREL_RD				GRAND_FIR_RD	Location:	NE		
ADA ID: A7E2F3E79DA7	Ramp Ty	Ramp Type: Perp				ail: Fail Overall C	o Severity Score:	22.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	1 2 2 2	Possible Solutions: Remove & Replace Entire Ramp.		Compliance Description			Data Compliance Description			Data
	and the second				N/A	Ramp Length (in)	48.5	No	Ramp Slope (%)	8.7
	Service of the				No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	2.5
· · · · · · · · · · · · · · · · · · ·	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
a t	10				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	IR RD	1			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
& &					N/A	Shared Landing?	N/A			
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1,	R304 2 2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	AL-	R304.5.3	1.004.2.2,		N/A	Painted X Walk1?	No		Painted X Walk2?	N/A
						X Walk 1 Direction	To S		X Walk 2 Direction	N/A
2011				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	GRAND FIR RD	-				X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good





