cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 20419	Main Str	Main Street: PARK_SOUTH_DR			ROYAL_CREST_DR	Location:	NE		
ADA ID: A7F57C93B7CF	Ramp Ty	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Cor			ompliance: No Severity Score		37.5
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance									
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	63.0	No	Ramp Slope (%)	10.1
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	7.0
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
KOYAL OREST OR		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
6				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
e de la constance de				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N MALL	Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	NA	,,,,,,,,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
ALL IN PROVIDENT	A MARSHE				X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
	1-1-			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PARK SOUTH DR				X Walk 1 Slope (%)	19.2		X Walk 2 Slope (%)	8.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	11.5
Street 2 Name	ROYAL CREST DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.7	N/A	Clear Space?	N/A
					Road X Slope (%)	16.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					21	N/A		, ,,	N/A
							Yes	Surface Condition? (G/P)	Good

1 Trans at 16

