

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5207	Main Street: HUBBARD_RD			Cross Street: HUBBARD_WOODS_RD				Location: N		
ADA ID: A80D96D03203	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Comp			oliance: No Severity Score:		12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
Possible Solutions:				Compliance Description Data C			Comp	Compliance Description		
	1	Remove & Replace Entire Ramp	-	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	9.3	
A A A A A A A A A A A A A A A A A A A				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.3	
	A The			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	Charles and	9		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
States States	X			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
the states		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
ADDESSA -	AL/A	\$		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
AN A COLOR S	Property in	N		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	A CANANA			N/A	Shared Landing?	N/A				
	the second	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Nor & and a	ar ar	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
I have the first the				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	Mar 1				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
have been as a second				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name HUBBARD	WOODS RD	_			X Walk 1 Slope (%)	4.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good





