

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

0.0

0.0

N/A

Intersection ID: 10017072 Main Street: UNIVERSITY CITY BV **Cross Street: N/A** Location: W **Overall Compliance: No** ADA ID: A811153F25CC Ramp Type: Directional1 Initial Pass/Fail: Fail **Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

N/A

N/A

Data

119.0

123.0

9.0

0.1

N/A N/A

Compliance Description

Grade Break?

Flare Type RT

Grade Break Slope (%)

Grade Break XSlope (%)



Street 1 Name	UNIVERSITY CITY BV
Stop Condition-Street 1	YieldSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions:	Comp	liance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
i i	Yes	Ramp Width (in)
	No	Ramp Slope (%)
	Yes	Ramp XSlope (%)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
Surveyor Notes:	N/A	Flare Traversable LT
N/A	N/A	Landing Length (in)
	N/A	Landing Width (in)
	N/A	Landing Slope (%)
	N/A	Landing X Slope (%)
PROW/ADA:	N/A	Landing Curb? (Y/N)
R304.2.2	N/A	Shared Landing?
	N/A	Gutter Ponding?
	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
		X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%
	N/A	Pamp incide VWalks

Tr. SALDING	



	5. S.			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	E E	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	Control of the contro			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	o central	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	TUNES	R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
A STATE OF THE PARTY OF THE PAR				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes		Road Slope (%)	6.9
Street 1 Name	UNIVERSITY CITY BV				X Walk 1 Direction	То Е		Road X Slope (%)	3.8
Stop Condition-Street 1	YieldSign				X Walk 1 Width (in)	102.0		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	6.9	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.8	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost:	\$ 1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	N/A
						,	•		