## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Curb Slope (%)

Good

14.5

		•									
Intersection ID: 16578	Main Street: CONWAY_AV				Cross Street: SCALEYBARK_RD				Location:	Ν	
ADA ID: A81959898170	Ramp Ty	Ramp Type: Combination2Diag			Initial Pass/Fail: Fail Overall Complian				nce: No Severity Score:		
Codes/Mitigation Info/Possible Solution Field Measu								rements/Component Compliance			
	S A BANY	Possible Solutions:			Compliance Description			Data Compliance Description		Data	
	Star III	Remove & Replace Curb	o Ram	n With	N/A	Ramp Length LT (in)	26.0		Ramp Length RT (in)	N/A	
	000	Two New Directional Ra			Yes	Ramp Width LT (in)	72.0	N/A	Ramp Width RT (in)	N/A	
Contraction of the second	A A	Equivalent.	•		Yes	Ramp Slope LT (%)	5.7	N/A	Ramp Slope RT (%)	N/A	
	201				Yes	Ramp XSlope LT (%)	1.5	N/A	Ramp XSlope RT (%)	N/A	
	1150				N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	8.8	
					Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.5	
SOM	S OF	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
BAR STRAND		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
A CONTRACTOR OF	3/				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	6.				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
9 m and 1					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
A A A A A A A A A A A A A A A A A A A	<u>6</u>	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
· · · · · · · · · · · · · · · · · · ·		Not Found, R304.2.2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
1	Mar and				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
A March					N/A	Shared Landing?	N/A				
	and the state of t				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	SCALEYBARK RD				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Street 2 Name	StopSign					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
Stop Condition-Street 2	CONWAY AV					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	1.3	
						X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	0.0	
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	3.0		Clear Space?	N/A	
						Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A	
		主法	-210		PPP -			N/A	Any Obstruction?	N/A	
SIUP		A CARACTER AND	Y	and the second second	a dig te				Obstruction Type		
			and the	4. 2 M G	with the					N/A	
			fine					N/A	Storm Grate/Utility Hazard?	N/A	
									Storm Grate/Utility Type		
										N/A	
	and the second s		the second s	Care of the local second				1 1/2 - 2		0	

and the second