

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

48.0

58.0

5.8

1.9

9.0

6.9

N/A

No

N/A

8.9

1.2

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 16.2

To NE

Intersection ID: 10021488 Main Street: BOSTON AV Cross Street: N/A Location: NW Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 0 **ADA ID: A86BCDDFCB41** Ramp Type: Combination1Diag

Compliance Description

Road X Slope (%)

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Compliance Description

Data

45.0



Street 1 Name StopSign Stop Condition-Street 1 N/A Street 2 Name None Stop Condition-Street 2 **BOSTON AV** Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes: N/A

Possible Solutions:

PROW/ADA

Not Found, R304.2.2, R304.5.3, R304.3.2

Total Cost:

Ramp Length RT (in) Ramp Length LT (in) Yes Ramp Width LT (in) 58.0 Yes Ramp Width RT (in) No Ramp Slope LT (%) 11.9 Yes Ramp Slope RT (%) Ramp XSlope LT (%) 0.9 Yes Ramp XSlope RT (%) Yes N/A Ramp Length (in) 26.0 Nο Ramp Slope (%) 48.0 No Ramp XSlope (%) Yes Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A Flare Slope LT (%) Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A N/A **DWS Contrast?** Landing Width (in) N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? Yes Painted X Walk2? To SE X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) 48.0 X Walk 2 Width (in) 1.7 X Walk 2 Slope (%) X Walk 1 Slope (%) X Walk 1 X Slope (%) 9.6 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? Yes Ramp inside XWalk2? Road Slope (%) 7.9 Clear Space?

4.5

N/A

N/A

N/A

Yes

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Any Obstruction?

Obstruction Type

Curb Slope (%)







3200.00