


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: N/A	Main Street: ELGIN_MOOR_RD	Cross Street: DOUGLAS_PALACE_CT	Location: NE
ADA ID: A888392A5867	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	50.0
			Yes	Ramp Width (in)	48.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
<p>Surveyor Notes:</p> <p>N/A</p>			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	1.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To SW
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	0.8
				X Walk 1 X Slope (%)	1.2
			N/A	Ramp inside XWalk1?	N/A
<p>PROW/ADA:</p> <p>R304.2.2, R304.5.3</p>			N/A	Road Slope (%)	N/A
				Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
<p>Street 1 Name</p> <p>Stop Condition-Street 2</p> <p>Street 2 Name</p> <p>Stop Condition-Street 1</p>	ELGIN MOOR RD				
	None				
	N/A				
	N/A				
<p>Total Cost:</p>	\$	1850.00			
<p>Compliance </p>	Description	Data	Compliance	Description	Data
No	Ramp Slope (%)	8.5			
No	Ramp XSlope (%)	3.4			
N/A	Flare Type RT	N/A			
N/A	Flare Slope RT (%)	N/A			
N/A	Flare Traversable RT?	N/A			
N/A	DWS Provided?	N/A			
N/A	DWS Contrast?	N/A			
N/A	DWS Length (in)	N/A			
N/A	DWS Full Width?	N/A			
N/A	DWS Offset (in)	N/A			
N/A	Gutter Slope (%)	N/A			
N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk2?	N/A			
	X Walk 2 Direction	N/A			
N/A	X Walk 2 Width (in)	N/A			
	X Walk 2 Slope (%)	N/A			
	X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk2?	N/A			
N/A	Clear Space?	N/A			
N/A	Clear Space to XWalk (in)	N/A			
N/A	Storm Grate/Utility Hazard?	N/A			
	Storm Grate/Utility Type				
N/A		N/A			
Yes	Surface Condition? (G/P)	Good			

