


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 52802		Main Street: TORP_LANDING_BV		Cross Street: CARNEGIE_BV		Location:		SE			
ADA ID: A891DF7EF2F7		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 12.5			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
				Possible Solutions:		Compliance		Description		Data	
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		35.5	
Surveyor Notes:				N/A		Yes		Ramp Width (in)		71.0	
						No		Ramp Slope (%)		9.7	
PROW/ADA:				R304.2.2		Yes		Ramp XSlope (%)		1.5	
						N/A		Flare Type LT		N/A	
						N/A		Flare Slope LT (%)		N/A	
						N/A		Flare Traversable LT?		N/A	
						N/A		Landing Length (in)		0.0	
						N/A		Landing Width (in)		0.0	
						N/A		Landing Slope (%)		0.0	
						N/A		Landing X Slope (%)		0.0	
						N/A		Landing Curb? (Y/N)		N/A	
						N/A		Shared Landing?		N/A	
						N/A		Gutter Ponding?		0.0	
						N/A		Gutter Lip Ht (in)		0.0	
						N/A		Painted X Walk1?		No	
						N/A		X Walk 1 Direction		To N	
						N/A		X Walk 1 Width (in)		N/A	
						N/A		X Walk 1 Slope (%)		2.9	
						N/A		X Walk 1 X Slope (%)		1.6	
						N/A		Ramp inside XWalk1?		N/A	
						N/A		Any Obstructions?		N/A	
						N/A		Obstruction Type		Yes	
						N/A		Surface Condition? (G/P)		Good	
						N/A		Curb Slope (%)		5.8	

