cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4129	Main Street: ANDREW_JAMES_DR			Cross Street: RENEE_SAVANNAH_LN				Location:	NE
ADA ID: A8BE4A81911E	BBE4A81911E Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No			Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
a the state	1 an and Some 3	Possible Solutions:		Compliance Description Data			Compliance Description		Data
		Remove & Replace	e Entire Ramp.	N/A	Ramp Length (in)	96.0	No	Ramp Slope (%)	10.4
	A Providence		•	No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	0.3
E E	A THERE	9		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	CIE OF			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
State State				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	The state	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
ANDRE	Annual State	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
and a second and a second and a second and a second a s			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
ESM EST			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
in Fine	The	Not Found, R304.	5.1. R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
all and a second second	,	,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
The state of the second				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	RENEE SAVANNAH LN				X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 18	350.00	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

