

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

3.0

60.0

8.4

1.8

3.8

1.4

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 48944Main Street: LILLYSHIRE_PLCross Street: CALDWELL_RIDGE_PYLocation:NWADA ID: A9542A811A94Ramp Type: Combination2Initial Pass/Fail: FailOverall Compliance: NoSeverity Score:22.5

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

N/A

N/A

N/A

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A N/A

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

Yes

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

Flare Traversable RT?

Flare Type RT

Data

5.5

59.0

2.1

3.2

47.0

47.5

N/A

N/A

N/A

N/A

N/A

N/A

N/A



Street 1 Name

Stop Condition-Street 1

Street 2 Name

None

CALDWELL RIDGE PY

N/A

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

CURB GAP 0.5", LT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.3.2



Total Cost:



1600.00

Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
X Walk 1 Direction	To E		X Walk 2 Direction	N/A
X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	N/A
Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	N/A		Clear Space?	N/A
Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
0		N/A	Any Obstruction?	N/A
			Obstruction Type	
				N/A
		N/A	Storm Grate/Utility Hazard?	N/A
			Storm Grate/Utility Type	
				N/A
		Yes	Surface Condition? (G/P)	Good
			Curb Slope (%)	21.5