


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: N/A	Main Street: SPRINGWOOD_ESTATE_DR	Cross Street: BELVEDERE_CASTLE_DR	Location: SW
ADA ID: A9A9BD68818E	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 0	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	Remove & Replace Entire Ramp.		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
			N/A	Ramp Length (in)	95.0
			Yes	Ramp Width (in)	48.0
			N/A	Flare Type LT	Sloped
			N/A	Flare Slope LT (%)	5.6
			N/A	Flare Traversable LT?	Yes
			Yes	Landing Length (in)	59.5
			Yes	Landing Width (in)	48.0
			Yes	Landing Slope (%)	1.1
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R305.2</p>			Yes	Landing X Slope (%)	1.4
			N/A	Landing Curb? (Y/N)	No
			N/A	Shared Landing?	No
			Yes	Gutter Ponding?	No
			Yes	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To E
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	6.9
				X Walk 1 X Slope (%)	0.9
<p>Street 1 Name</p> <p>Stop Condition-Street 2</p> <p>Street 2 Name</p> <p>Stop Condition-Street 1</p>			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	N/A
				Road X Slope (%)	N/A
			Yes	Any Obstructions?	No
				Obstruction Type	
			N/A		
			Yes	Surface Condition? (G/P)	Good
Total Cost:		\$ 1850.00			

