

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10032191	2191 Main Street: MORRISON_BV				N/A	Location:	SE		
ADA ID: A9AEC8FEDBFF				Initial Pass/Fail: Fail Overall Compliance: No					1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:							liance Description	Data	
5	V /23	Remove & Replace Entire Ram	n.	N/A	Ramp Length (in)	36.0	N/A	Grade Break?	N/A
	1220 20		P .	Yes	Ramp Width (in)	63.0	N/A	Grade Break Slope (%)	0.0
	Garage Content			Yes	Ramp Slope (%)	6.3	N/A	Grade Break XSlope (%)	0.0
A Less	<u>E.</u>			No	Ramp XSlope (%)	3.6			
	Can and			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
G. C.	la in			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	A.	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
ALL CALL				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	- AND -			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	and a	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	1 an an an an an			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
- Or William	1 Jacob			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	9.7			N/A	Painted X Walk1?	No		Road Slope (%)	0.8
Street 1 Name	ENTRANCE				X Walk 1 Direction	To NW		Road X Slope (%)	1.4
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	0.8	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.4	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	16.0

