## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14959	Main Street: REDDMAN_RD			Cross Street: CENTRAL_AV					Location:	w	
ADA ID: AA3284B8F141				Initial Pass/Fail: Fail Overall Compliance: No						10	
· · · ·									10		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
and the second s	5	Possible Solutions:		Compliance Description			Data Compliance Description			Data	
		Remove & Replace Ent	ire Ramp		N/A	Ramp Length (in)	74.0	Yes	Ramp Slope (%)	6.9	
					No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	4.4	
a star a star					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
CENT CENT	5 B. S				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
and a second second	S Store				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	K N Ra				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
1 - 15		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
L.		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
And A					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
A State State	3 B			N/A	Shared Landing?	N/A					
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.5.1, F	R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
ALE SHOTHER AND	Line and the second sec				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
7-10 1111 31 31						X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
11111110				N/A	X Walk 1 Width (in)	111.0	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name	CENTRAL AV					X Walk 1 Slope (%)	4.8		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	<b>\$</b> 1	850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	
								1			

Yes Surface Condition? (G/P)

Good



