cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 42789 Main Street: CALDWELL_CROSSING_PY					eet:	TIMBER_RIDGE_RD	Location:	S		
ADA ID: AA57D03AA8	8F Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Compliance				ce: No Severity Score: 10		10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description		Data Compliance Description			Data	
and the second		Remove & Replace Enti	re Ramp.	N	/ A	Ramp Length LT (in)	43.0	N/A	Ramp Length RT (in)	44.0
	I PROST CON			Y	es	Ramp Width LT (in)	59.5	Yes	Ramp Width RT (in)	61.0
				Y	es	Ramp Slope LT (%)	5.2	Yes	Ramp Slope RT (%)	6.1
	A CONTRACTOR			Ν	lo	Ramp XSlope LT (%)	2.4	No	Ramp XSlope RT (%)	2.6
				Ν	I/A	Ramp Length (in)	45.5	Yes	Ramp Slope (%)	5.3
	CALDINAL			N	lo	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	1.5
States and a state of the state	CROSS-	Surveyor Notes:		N	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	t.	N/A		N	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	ALL			Ν	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	- Station -			Ν	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	and a state of the second			Ν	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		PROW/ADA:		Ν	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Not Found, R304.5.1, R3			304.5.3	N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	warter aller and			N	I/A	Shared Landing?	N/A			
					I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign			N	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	CALDWELL CROSSING PY			N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$ 180	00.00 N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
	1944 ·				121			N/A	Any Obstruction?	N/A
		The same	a state	State 1					Obstruction Type	
		and a state of the	I		A DECEMBER OF				• •	N/A
			4 Mar					N/A	Storm Grate/Utility Hazard?	N/A
		at a second at the				11			Storm Grate/Utility Type	n/A
					Contraction of the second					N1/A

N/A Surface Condition? (G/P) Yes Good Curb Slope (%) 10.7





