

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 42748 Main Street: BACK\_ACRE\_DR **Cross Street: BARCLAY FOREST DR** Location: N/A ADA ID: AA69DD6A0EDD Ramp Type: NoRamp Initial Pass/Fail: NoRamp Overall Compliance: No **Severity Score:** 100

**Codes/Mitigation Info/Possible Solution** 

Field Measurements/Component Compliance Data Compliance Description



**Provide Curb Ramp Remove &** Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

N/A

Total Cost: 1500.00





