

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

N/A

N/A

N/A

N/A

6.2

2.6

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: ARCHDALE DR Intersection ID: 19986 **Cross Street: SOUTH BV** Location: NW Initial Pass/Fail: Fail **Overall Compliance: No ADA ID: AA6CFC5BB8FB** Ramp Type: Combination2 Severity Score: 13.75

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

Yes

No

No

N/A

Yes N/A

**Codes/Mitigation Info/Possible Solution** 

## **Field Measurements/Component Compliance**

N/A

N/A

N/A

N/A

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

55.0

96.0

8.8

2.9

28.5

48.0

N/A



Street 1 Name Signal ARCHDALE DR Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A

"	Fossible Solution
	Possible Solutions:
	Remove & Replace Entire Ramp.
	Surveyor Notes:
	N/A
	PROW/ADA:
	Not Found, R304.5.3, R304.3.2
ķ	
_	



Total Cost:



N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	116.0		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A
1600.00 N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
ALLEY AND ALLEY			N/A	Any Obstruction?	N/A
	1			Obstruction Type	
					N/A
ALERS CO. CO. C.			N/A	Storm Grate/Utility Hazard?	N/A
			Storm Grate/Utility Type		
				N/A	
			Yes	Surface Condition? (G/P)	Good
A AMARIA				Curb Slope (%)	13.1