


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 17400		Main Street: BAINBRIDGE_RD		Cross Street: VISTA_DR		Location:		SE									
ADA ID: AA6E23BFFBD4		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 1.25									
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance													
				Possible Solutions:		Compliance		Description		Data							
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		89.0		N/A					
Surveyor Notes:				N/A		Yes		Ramp Width (in)		60.0							
						Yes		Ramp Slope (%)		0.5							
PROW/ADA:				R304.5.3		No		Ramp XSlope (%)		2.2							
						N/A		Flare Type LT		N/A							
Street 1 Name				VISTA DR		N/A		Flare Slope LT (%)		N/A							
				StopSign		N/A		N/A		Flare Type RT		N/A					
Street 2 Name				N/A		N/A		Flare Traversable LT?		N/A							
				N/A		N/A		N/A		Flare Traversable RT?		N/A					
Stop Condition-Street 1						N/A		Landing Length (in)		0.0							
						N/A		N/A		Landing Width (in)		0.0					
Stop Condition-Street 2						N/A		N/A		DWS Provided?		N/A					
						N/A		N/A		N/A		DWS Contrast?		N/A			
Total Cost:				\$ 1600.00		N/A		N/A		DWS Length (in)		N/A					
						N/A		N/A		N/A		DWS Full Width?		N/A			
						N/A		N/A		N/A		DWS Offset LT (in)		N/A			
						N/A		N/A		N/A		N/A		DWS Offset RT (in)		N/A	
						N/A		N/A		N/A		N/A		Gutter Slope (%)		N/A	
						N/A		N/A		N/A		N/A		N/A		Gutter X Slope (%)	
						N/A		N/A		No		Road Slope (%)		4.8			
						N/A		N/A		To NW		Road X Slope (%)		1.1			
						N/A		N/A		N/A		Clear Space?		N/A			
						N/A		N/A		N/A		N/A		Clear Space to XWalk (in)		N/A	
						N/A		N/A		N/A		N/A		Storm Grate/Utility Hazard?		N/A	
						N/A		N/A		N/A		N/A		Storm Grate/Utility Type			
						N/A		N/A		N/A		N/A		Surface Condition? (G/P)		Good	
						N/A		N/A		N/A		N/A		Curb Slope (%)		16.5	

