

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 10038508 Main Street: SPEER\_BV Cross Street: PIEDMONT\_PARK\_DR Location: N **Overall Compliance: No** ADA ID: AA755FA686B4 Ramp Type: Directional1 Initial Pass/Fail: Pass **Severity Score:** 0.25

Codes/Mitigation Info/Possible Solution



Street 1 Name **SPEER BV** Stop Condition-Street 1 None Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solution	
Possible Solutions:	Co
Remove & Replace Entire Ramp.	N/A
·	Yes
	Yes
	No
	Yes
	N/A
Surveyor Notes:	N/A
N/A	Yes
	Yes
	Yes
	Yes
PROW/ADA:	N/A
R304.5.3, R305.2	N/A
·	Yes
	Yes
	N/A

Total Cost:	\$ 1600.00

Field Measurements/Component Compliance							
Compl	iance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	70.0	Yes	Grade Break?	Yes		
Yes	Ramp Width (in)	70.0	Yes	Grade Break Slope (%)	2.3		
Yes	Ramp Slope (%)	5.0	No	Grade Break XSlope (%)	2.5		
No	Ramp XSlope (%)	2.6					
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No		
Yes	Landing Length (in)	70.0	Yes	DWS Provided?	Yes		
Yes	Landing Width (in)	70.0	Yes	DWS Contrast?	Yes		
Yes	Landing Slope (%)	0.1	Yes	DWS Length (in)	24.0		
Yes	Landing X Slope (%)	1.5	Yes	DWS Full Width?	Yes		
N/A	Landing Curb? (Y/N)	No	No	DWS Offset LT (in)	12.0		
N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	27.5		
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.4		
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.2		
N/A	Painted X Walk1?	No		Road Slope (%)	2.7		
	X Walk 1 Direction	To SE		Road X Slope (%)	2.1		
	X Walk 1 Width (in)	N/A		Clear Space?	Yes		
	X Walk 1 Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A		
	X Walk 1 X Slope (%)	2.1	Yes	Storm Grate/Utility Hazard?	No		
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type			
Yes	Any Obstructions?	No			N/A		
	Obstruction Type		Yes	Surface Condition? (G/P)	Good		
		N/A	N/A	Curb Slope (%)	5.4		





