


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 53191	Main Street: JOHNSTON_OEHLER_PRIVATE_DR	Cross Street: JOHNSTON_OEHLER_RD	Location: SE
ADA ID: AA7A76FF8680	Ramp Type: BlendTrans1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 1.25	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	104.0	Yes	BlendTrans Slope (%)	4.2
			Yes	Ramp Width (in)	60.0	No	BlendTrans XSlope (%)	2.8
			N/A	Flare Type	LT_Curbed_NoWalkSurface	N/A	Flare Type	RT_Curbed_NoWalkSurface
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
			N/A	Landing Length (in)	80.0	N/A	DWS Provided?	Yes
			N/A	Landing Width (in)	60.0	N/A	DWS Contrast?	Yes
			N/A	Landing Slope (%)	0.4	N/A	DWS Length (in)	24.0
			N/A	Landing X Slope (%)	1.6	N/A	DWS Full Width?	Yes
Surveyor Notes:		N/A	N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
PROW/ADA:		R304.5.3	N/A	Shared Landing?	No			
			N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	1.6
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	0.5
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A
				X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	0.1		Clear Space?	Yes
				Road X Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	No	N/A	Storm Grate/Utility Hazard?	No
				Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good
						N/A	Curb Slope (%)	N/A

