## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17246	Main Str	Main Street: SCALEYBARK_RD			SHADOW_ELM_DR		Location:			
ADA ID: AABE1B4EE77E	Ramp Ty	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Comp			liance: No Severity Score:		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	ALL	Possible Solutions:		Compliance Description		Data	Data Compliance Description			
1 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- 257 3	Remove & Replace Entire Ram	).	N/A	Ramp Length (in)	158.0	N/A	Grade Break?	N/A	
A Charles P	8			Yes	Ramp Width (in)	59.0	N/A	Grade Break Slope (%)	0.0	
	5 6			No	Ramp Slope (%)	9.8	N/A	Grade Break XSlope (%)	0.0	
G. Law				No	Ramp XSlope (%)	2.2				
	S A B			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
the second second	E.			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
Contraction of the second s		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
the second se	a freedom and	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	1 CARLEY			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	ALL BANK			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	it.			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	1 1 A A A A A	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
A A A A A A A A A A A A A A A A A A A		R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
A CARAGE	19107 1 23	,		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
C. T. A. C. A. C. A.	1 198 2			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
「二、二、二、二、二、二、二、二、二、二、二、二、二、二、二、二、二、二、二、	A CEVERAL			N/A	Painted X Walk1?	No		Road Slope (%)	2.6	
Street 1 Name	SHADOW ELM DR				X Walk 1 Direction	To SE		Road X Slope (%)	6.0	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	6.0	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	12.2	

