

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8323Main Street: JENNINGS_STCross Street: CATHERINE_SIMMONS_AVLocation:NEADA ID: AAC1D393022ERamp Type: PerpInitial Pass/Fail: PassOverall Compliance: NoSeverity Score:10

Codes/Mitigation Info/Possible Solution



Street 1 Name

Stop Condition-Street 2

StopSign

Street 2 Name

N/A

Stop Condition-Street 1

N/A

<u> </u>	1 CCCIBIC CCIGNON	
Sec. of	Possible Solutions:	Co
	Remove & Replace Entire Ramp.	N/A
1		Ye
		N/A
SALES OF		N/A
No.		N/A
A 47 %		No
	Surveyor Notes:	No
	N/A	No
1		No
7		N/A
		N/A
	PROW/ADA:	Ye
	Not Found, R304.2.1, R304.2.2-Perp,	Ye
1	R304.3.2-Para, R304.5.3	N/A
No.		
		N/A
		N/A





Total Cost:



1850.00

Field Measurements/Component Compliance								
Compliance Description Data			Comp	liance Description	Data			
N/A	Ramp Length (in)	41.0	Yes	Ramp Slope (%)	5.4			
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.4			
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	2.0	Yes	Flare Slope RT (%)	1.5			
N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes			
No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes			
No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes			
No	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.5			
No	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes			
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0			
N/A	Shared Landing?	No						
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.3			
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.7			
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	Yes			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			