

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.2

7.5

N/A

N/A

Intersection ID: 10019931 Main Street: ARDREY KELL RD Cross Street: N/A Location: NW Initial Pass/Fail: Fail **Overall Compliance: No** 25 ADA ID: AAE58052B2EA Ramp Type: Perp **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

Data

85.0

48.0

N/A

N/A



Possible Solutions:	Compli	iance	Description
Remove & Replace Entire Ramp.	N/A	Ram	c Length (in)
·	Yes	Ramp Width (in)	
	N/A	Flare	Type LT
	N/A	Flare	Slope LT (%)
	N/A	Flare	Traversable L
	N/A	Land	ing Length (in)
Surveyor Notes:	N/A	Land	ing Width (in)
N/A	N/A	Land	ing Slope (%)
	N/A	Land	ing X Slope (%
	N/A	Land	ing Curb? (Y/N
	N/A	Share	ed Landing?
PROW/ADA:	N/A	Gutte	er Ponding?
Not Found, R304.5.3	N/A	Gutte	er Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	lk 1 Direction
	N/A	X Wa	lk 1 Width (in)
		X Wa	ilk 1 Slope (%)
		X Wa	lk 1 X Slope (%
	NI/A	Dami	o incido VMalka





