

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 53227 Main Street: MAJOR SAMUALS WY **Cross Street: EVERGREEN_DR** Location: SW **Overall Compliance: No** ADA ID: AAF6179C0251 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 10

Codes/Mitigation Info/Possible Solution



MAJOR SAMUALS WY Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	<u>c</u>		
Remove & Replace Entire Ramp.			
	N		
	N		
	N		
	N		
	N		
Surveyor Notes:	N		
N/A			
	N		
	N		
	N		
PROW/ADA:	N		
Not Found, R304.5.1, R304.5.3			
	N		
	N		

Total Cost: 1850.00

Field Measurements/Component Compliance								
Compl	iance Description	Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	68.5	Yes	Ram	o Slope (%)	7.8		
No	Ramp Width (in)	47.5	No	Ramp	xSlope (%)	2.1		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To N		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	ılk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	4.4		X Wa	ılk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	0.1		X Wa	ılk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	p inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storn	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ice Condition? (G/P)	Good		





